3.2 USDA Report

In accordance with the USDA requirements, all temperatures are printed out automatically at selected time intervals and by the printer decided for USDA printout.

STOPPED	MONITOR	Picture name	15K 25/03/92 12:10 UTC

No.	Status		Sensor no. 1	2	3	4	5	6	7	8	9	USDA zone
1A	A__	ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9				A
1B/C	_D_	OFF	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	B
2A/B	__I	ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	C
2C/D	___	OFF	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	D
3A/B	__I	ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	E
3C/D	A__	ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	F
4A/B	A__	ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	G
4C/D	_D_	OFF	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	H

Hold	Machinery	Alarm-System	Common	System

The sensor No. refers to USDA sensor arrangement drawing.

Status refers to the following alarm suppressions:

   I = Inhibit
   D = Defrost
   A = Alarm
   ON/OFF = Regulation status

A '*' located in front of a value at the printout indicates that an alarm condition exists for this particular sensor.

UTC means : Universal Time Coordinated

LMT means : Local Mean Time

More detailed description in Operators Manual ch. 2.7