


■ : USDA TEMP FIXED TYPE PTL 100
 ○ : USDA TEMP FLEXIBLE TYPE PTI 100



REV NO

DRAWING NO

220 901

USDA SENSOR ARRANGEMENT

AALBORG 247 - 249

CLIENT

DRAWN JHA 840416

CHECKED

APPROVED

SCALE


SABROE

P. O. BOX 1810, 8270 HØJBJERG, DENMARK
 PHONE: (06) 2712 06 TELEX: 68 740 SABROEDK
 CABLE: SABROE AARHUS


CABLE: SABROE AARHUS

220 901







FCL1 = 840 m³




UTD4 = 861 m³




UTD3 = 1060 m³




UTD2 = 1041 m³




UTD1 = 516 m³




LTD4 = 560 m³




LTD3 = 941 m³




LTD2 = 881 m³




LTD1 = 417 m³



UH3 = 942 m³



UH2 = 821 m³




Δ: RETURN AIR TEMP
TYPE PTV 100


⊕: DELIVERY AIR TEMP
TYPE PTR 100 (DOUBLE)

□: RH% SENSORS

LH3 = 885 m³



LH2 = 679 m³



220 902

AIRCOOLER AND HOLD SENSORS
ARRANGEMENT

AALBORG 247 - 249

DRAWN: JHA 840416
CHECKED

APPROVED
SCALE

SABROE

P O BOX 1810 8270 HOJBJERG DENMARK
PHONE 06 2712 66 TELEX 68 740 SABROE DK
CABLE SABROE AARHUS

