

DATALOGGER SYSTEM

Hold No	PORTABLE SENSOR RETURN AIR	PORTABLE SENSORES IN CARGO HOLD	PORTABLE SENSOR DELIVERY	
1A	2113	0114 0115 0116 0117 0118	1111 1112	RA DA RH
1B	2123	0124 0125 0126 0127 0128	1121 1122	RA DA RH
1C	2133	0134 0135 0136	1131 1132	RA DA RH
1D	2143	0144 0145 0146	1141	RA DA RH
2A	2213	0214 0215 0216 0217 0218	1211 1212	RA DA RH
2B	2223	0224 0225 0226 0227 0228	1221 1222	RA DA RH
2C	2233	0234 0235 0236 0237 0238	1231 1232	RA DA RH
2D	2243	0244 0245 0246 0247 0248	1241 1242	RA DA RH
3A	2313	0314 0315 0316 0317 0318	1311 1312	RA DA RH
3B	2323	0324 0325 0326 0327 0328	1321 1322	RA DA RH
3C	2333	0334 0335 0336 0337 0338	1331 1332	RA DA RH
3D	2343	0344 0345 0346 0347 0348	1341 1342	RA DA RH
4A	2413	0414 0415 0416 0417 0418	1411 1412	RA DA RH

