

4.2 USDA Report

In accordance with the USDA requirements, all temperatures are printed out automatically at selected time intervals and by the printer decided for USDA printout.

RUNNING	Monitoring	USDA report page 1	YY/MM/DD 00:00:00 UTC
---------	------------	--------------------	-----------------------

No.	Status	Sensor no.								
		1	2	3	4	5	6	7	8	
1A	A ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	
1B	D OFF	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	
1C	D OFF	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	
2A	I ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9
2B	I ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9
2C	A ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9
2D	PDOWN	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9
2E	L ON	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9	-99.9

The sensor No. refers to USDA sensor arrangement drawing: ²⁶²⁷⁴⁷ ~~20000002~~

Status refers to the following alarm suppressions:

- I Inhibit
- D Defrost
- A Alarm in the deck

Alarm conditions are marked with an asterisk "*".

UTC means: Universal Time Coordinated

More detailed description in Operator's Manual