

USDA REPORT 04/05 23:55 (G.M.T)

SENSORS NO.

HOLD	1	2	3	4	5	6	7	8	9	10
1A	12.5	14.6	12.8	12.8	15.1	14.6				
1BC	10.2	10.5	10.3	11.0	10.3	10.4	10.2	10.4		
2AB	10.1	.0	13.5	.2	.7	.1	.1	.1	.6	
2CD	.8	.1	-.1	.8	.1	.0	.0	-.2	.0	
3AB	.0	.0	-.1	.1	.1	.0	.0	-.1	.0	
3CD	.0	.3	.1	.1	.1	-.2	.1	-.1	.2	
4AB	18.7	18.9	11.3	18.3	18.6	18.9	10.8	10.8	10.7	
4CD	10.1	12.1	11.4	10.9	11.2	11.4	10.2	10.7	11.2	

3ABCD

USDA REPORT 04/05 23:58 (G.M.T)

SENSORS NO.

HOLD	1	2	3	4	5	6	7	8	9	10
1A	12.5	14.7	12.8	12.9	15.2	14.7				
1BC	.2	.1	-.2	.2	.2	.0	.2	.0		
2AB	10.1	.0	13.6	.1	.7	.1	.0	.0	.5	
2CD	.8	.1	-.1	.8	.1	.0	.0	-.2	.0	
3AB	.0	.0	-.1	.1	.0	.0	.0	-.1	.0	
3CD	-.1	.1	.1	.0	.1	-.2	.1	-.2	.1	
4AB	19.0	19.0	11.4	18.5	18.6	19.3	10.8	10.8	10.8	
4CD	10.2	12.5	11.5	10.9	11.3	11.4	10.4	10.6	11.2	

#1

USDA REPORT 04/06 00:00 (G.M.T.)

SENSORS NO.

HOLD	1	2	3	4	5	6	7	8	9	10
1A	.2	1.7	.1	.3	1.5	1.1				
1BC	.0	.1	-.2	.1	.0	.0	.0	.0		
2AB	10.1	.0	13.7	.1	.6	.1	.0	.0	.5	
2CD	.8	.1	-.1	.8	.1	.0	.0	-.1	.0	
3AB	.0	.0	-.1	.1	.1	.0	.0	-.1	.0	
3CD	-.1	.0	.0	.0	.1	-.2	.0	-.2	.1	
4AB	19.1	19.0	11.4	18.6	18.7	19.4	10.9	10.9	10.9	
4CD	10.5	12.6	11.6	10.9	11.4	11.6	10.4	10.6	11.2	

#2

1ABC

USDA REPORT 04/06 00:26 (G.M.T)

SENSORS NO.

HOLD	1	2	3	4	5	6	7	8	9	10
1A	.0	.1	.0	.1	.2	.1	.0	.0	.0	
1BC	-.1	.1	-.2	.1	.0	-.1	.0	.0	.0	
2AB	-.1	.0	.0	.0	.1	.0	.0	-.1	.1	
2CD	.5	.1	-.1	.6	.2	.0	.1	-.1	.0	
3AB	9.1	11.1	10.4	10.7	9.9	10.5	10.1	9.7	11.1	
3CD	7.5	9.7	9.8	9.9	8.4	9.7	9.8	11.0	12.7	
4AB	19.7	19.3	12.1	19.8	19.0	19.8	11.5	11.5	11.9	
4CD	11.3	13.1	12.2	11.2	11.8	11.6	11.1	10.8	11.6	

#1