Ivory Dawn
Hull No. 862













AIR SENSORS (FIXED)

SHALL BE LOCATED ON THE CENTERLINE OF THE VESSEL, APPROXIMATELY 30 CENTIMETERS FROM THE CEILING.

SHALL BE ATTACHED IN SUCH A WAY THAT THEY DON'T TOUCH THE BULKHEAD AND ARE PROTECTED FROM DAMAGE CAUSED BY THE CARGO.

FRUIT SENSORS (PORTABLE)

SHALL BE STOWED IN RECESSED BOXES TO BE PROTECTED FROM DAMAGE WHEN NOT IN USE.

PROPOSAL OF BOXES FOR USDA FRUIT SENSORS, SEE DRAWING F-22731.

SYMBOL	QUANTITY	DESCRIPTION
Δ	30	USDA AIR SENSOR, FIXED
Δ~	74	USDA FRUIT SENSOR, PORTABLE

SNO 858, 862, 863, 864
14726 m³ REEFER VESSEL
YARO: SHIKOKU, JAPAN
STAL'S NO: B-9673.0076
B-0673.0052
B-0673.0053
B-0673.0054

UNITED STATES DEPARTMENT OF AGRICULTURE
Animal and Plant Health Inspection Service
Plant Protection and Quarantine
APPROVED
Date

Nr	Införd	Ändringar
a	91.02.26	BN Additional vessels SNO 862,863,864

Infört ändringsskede Alteration No.	Ritad Drawn	Kontrollerad Checked	Godkänd Approved	Arkivnummer Archive No.	DF	UGF
a	89.12.11					

STAL REFRIGERATION SWEDEN

LOCATION OF USDA TEMPERATURE SENSORS IN CARGO SPACE

Ark nr Sheet No. | Ant. ark Tot. No. of sh.

9673.0076-14A

M/V IVORY DAWN