



Current User:
reefer



Greenco

7/24/2013 06:13:08






Messina Strait
MO#9267546

USDA Deck 01

Ventilation

Cooling




Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

	Date	Time	Number	WinCC Message text
▶ 26	24/07/13	06:10:22 AM	3450	Connection lost PLC11 USDA02

Alt F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
------------------------------	------------------------	-------------------	--------------------	-------------------	-----------------	---------------------	------------------	------------------------------	-----------------------------	--------------------------



Current User:
reefer






7/24/2013 06:12:11



USDA Deck 02

Ventilation

Cooling



Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

	Date	Time	Number	WinCC Message text
26	24/07/13	06:10:22 AM	3450	Connection lost PLC11 USDA02

Alt F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
-----------------------	--------------------	------------	-------------	------------	----------	--------------	-----------	--------------------------	-------------------------	----------------------



Current User:
reefer



Greenco




7/24/2013 06:11:55



USDA Deck 03

Ventilation

Cooling



Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

Date	Time	Number	WinCC Message text
24/07/13	06:10:22 AM	3450	Connection lost PLC11 USDA02

F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
----------------	-----------------	------------	-------------	------------	----------	--------------	-----------	-----------------------	----------------------	-------------------



Current User:
reefer



Greenco




7/24/2013 06:11:39



USDA Deck 04

Ventilation

Cooling



Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

Date	Time	Number	WinCC Message text
24/07/13	06:10:22 AM	3450	Connection lost PLC11 USDA02

Alt F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
--------------------	-----------------	------------	-------------	------------	----------	--------------	-----------	-----------------------	----------------------	-------------------



Current User:
reefer



Granco




7/24/2013 06:11:01



USDA Deck 05

Ventilation

Cooling



Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

	Date	Time	Number	WinCC Message text
26	24/07/13	06:10:22 AM	3450	Connection lost PLC11 USDA02

Alt F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
--------------------	-----------------	------------	-------------	------------	----------	--------------	-----------	-----------------------	----------------------	-------------------



Current User:
reefer




7/24/2013 06:10:49





USDA Deck 06

Ventilation

Cooling



PS



SB

Deck 01	Deck 02	Deck 03	Deck 04	Deck 05	Deck 06	Sensor Settings
---------	---------	---------	---------	---------	---------	-----------------

Date	Time	Number	WinCC Message text
24/07/13	06:10 22 AM	3450	Connection lost PLC11 USDA02

Alt F1: Log In/Out	F2: Main Screen	F3: Alarms	F4: Reports	F5: System	F6: USDA	F7: Products	F8: Table	F9: Decks Alarm Reset	F10: ECR Alarm Reset	F11: Print Screen
--------------------	-----------------	------------	-------------	------------	----------	--------------	-----------	-----------------------	----------------------	-------------------

