



■ = USDA TEMP FIXED TYPE
PTL 100 (SABROE SUPPLY)
○ = USDA TEMP FLEXIBLE TYPE
PTI 100 (SABROE SUPPLY)

| | | | |
|-----|----------|-----|-----|
| REV | DATE | INT | ECN |
| L | 53 05 15 | 382 | |

880527 330315



SABROE
P. BOX 1810 8270 HOJBERG DET. MAR.
DEN. TEL. 66 27 1266 TELE X. 68 740 SABROE DA
CABLE SABROE COPENHAGEN

Arctic Goose
Hull No. 202

USDA SENSOR ARRANGEMENT

DRAWING NO.
241185

REV. NO.
L