

△	43	USDA TEMP. SENSOR PORTABLE	TYPE: PT-100
△	12	USDA FIXED TEMPERATURE SENSOR	
▲	8	USDA FIXED TEMP. SENSOR/DATALOG TEMP. SENSOR, RETURN	
●	8	CONTROL TEMP. SENSOR/DATALOG TEMP. SENSOR, DELIVERY	
○	8	DATALOG TEMP. SENSOR DELIVERY	
⊗	8	RELATIV HUMIDITY SENSOR DATALOG	
□	8	CO2 MEASURING PIPE INLET DATALOG	

