

FIXED SENSOR WITH 2.5 MTR. OF CABLE
FOR MEASURING AIR TEMPERATURE
TYPE: OTP-17045-PT100-2500 SEE DRAW E-81



MOVABLE SENSOR WITH 12 MTR. OF CABLE
FOR MEASURING BARGO TEMPERATURE
TYPE: OTP-17045-PT100-12000 SEE DRAW. E-81

HOLD 1A — 900 M 3
HOLD 1B — 857 M 3
HOLD 2A — 1147 M 3

HOLD 3A/B/4A/B E-80 SH 2	HOLD 1A/1B/2A/B E-80 SH 1
HOLD 3C/D/4C/D E-80 SH 4	HOLD 1B/C/2C/D E-80 SH 3

POSITIONS OF TEMPERATURE SENSORS TO MEET U.S.D.A. REQUIREMENTS

NO.	DATE	SIGN.	DESCRIPTION ALTERATION	DATE	NAME	MADE FOR:	DESCRIPTION:	U.S.D.A. HOLD 1A, 1B/C (UPPER), 2A/B	THE NETHERLANDS COPYRIGHT reserved by IAW	SIZE: A3	DRAWING NO: 05.03.506-E-80	SHEET: 01/04
				04-04-91	M.E.	VAN DIEPEN BN 1094						
				03-05-1991								



FIXED SENSOR WITH 2.5 mtr. OF CABLE
FOR MEASURING AIR TEMPERATURE
TYPE: QTP-17045-P1100-2500 SEE DRAW E-81

MOVABLE SENSOR WITH 12 mtr. OF CABLE
FOR MEASURING GARGO TEMPERATURE
TYPE: QTP-17045-P1100-12000 SEE DRAW. E-81



HOLD 2BQ — 857 M 3
HOLD 2DQ — 1245 M 3

HOLD 3AB/4AB E-80 SH 2	HOLD 1A/1BQ/2AB E-80 SH 1
HOLD 3CD/4CD E-80 SH 4	HOLD 1BQ/2CD E-80 SH 3

POSITIONS OF TEMPERATURE SENSORS TO MEET U.S.D.A. REQUIREMENTS

NO.	DATE	SIGN.	DESCRIPTION ALTERATION	DATE	NAME	MADE FOR:	DESCRIPTION:	THE NETHERLANDS copyright reserved by law	SIZE: A3	DRAWING NO: 05.03.506-E-80	SHEET: 03/04
				04-04-91	M. E.	VAN DIEPEN BN 1034	U.S.D.A. HOLD 1BC (LOWERS) . 2CD				
										ORDER No: 05.03.506	





FIXED SENSOR WITH 2.5 mtr. OF CABLE
 FOR MEASURING AIR TEMPERATURE
 TYPE: OTP-17045-PT100-2500 SEE DRAW E-81

MOVABLE SENSOR WITH 12 mtr. OF CABLE
 FOR MEASURING BARBO TEMPERATURE
 TYPE: OTP-17045-PT100-12000 SEE DRAW. E-81

HOLD 3AB — 1059 M 3
 HOLD 4AB — 1301 M 3



HOLD 3AB/4AB E-80 SH 2	HOLD 1A/1BC/2AB E-80 SH 1
HOLD 3CD/4CD E-80 SH 4	HOLD 1BC/2CD E-80 SH 3

POSITIONS OF TEMPERATURE SENSORS TO MEET U.S.D.A. REQUIREMENTS

NO.	DATE	SIGN.	DESCRIPTION ALTERATION	DATE	NAME	MADE FOR:	DESCRIPTION	SIZE:	DRAWING NO:	SHEET:
				04-04-91	M. E.	U.S.D.A. HOLD 3AB, 4AB	THE NETHERLANDS	A3	05.03.506-E-80	02/04
				03-05-1991						



ORDER NO: 05.03.506
 SHEET: 02/04



FIXED SENSOR WITH 2.5 mtr. OF CABLE
FOR MEASURING AIR TEMPERATURE
TYPE: QTP-17045-PT100-2500 SEE DRAW E-81

MOVABLE SENSOR WITH 12 mtr. OF CABLE
FOR MEASURING BARBO TEMPERATURE
TYPE: QTP-17045-PT100-12000 SEE DRAW. E-81

HOLD 3CD — 1271 M 3
HOLD 4CD — 999 M 3

HOLD 3AB/4AB E-80 SH 2	HOLD 1A/1BC/2AB E-80 SH 1
HOLD 3CD/4CD E-80 SH 4	HOLD 1BC/2CD E-80 SH 3

POSITIONS OF TEMPERATURE SENSORS TO MEET U.S.D.A. REQUIREMENTS

NO.	DATE	SIGN.	DESCRIPTION ALTERATION	DATE	NAME	MADE FOR:	DESCRIPTION:	THE NETHERLANDS COPYRIGHT reserved by law	SIZE: A3	DRAWING NO: 05.03.506-E-80	SHEET: 04/04
				04-04-91	M. E.	VAN DIEPEN, BN 1034	U.S.D.A. HOLD 3CD, 4CD				
				03-05-1991						ORDER NO: 05.03.506	



THE NETHERLANDS
COPYRIGHT reserved by law