

```
09:32:15] GRENCO GOVERNING SYSTEM ]^ CALA PEVERO ^level: 5
20:03:10 LS5 :EEPROM Failure :
17/01/90 09:32 USDA REPORT, HOLD 1D+2D PAGE: 4
S1700 : 7.0 C 1D1 air temp. sensor
S1800 : 0.0 C 1D2 air temp. sensor
S1701 : 0.0 C 1D3 pulp temp. sensor
S1801 : 0.0 C 1D4 pulp temp. sensor
S1702 : 0.0 C 1D5 pulp temp. sensor
S1802 : 0.0 C 1D6 pulp temp. sensor
S1703 : 7.2 C 2D1 air temp. sensor
S1803 : 6.7 C 2D2 air temp. sensor
S1704 : 6.7 C 2D3 pulp temp. sensor
S1804 : 6.9 C 2D4 pulp temp. sensor
S1705 : 6.9 C 2D5 pulp temp. sensor
S1805 : 6.4 C 2D6 pulp temp. sensor
S1706 : 6.7 C 2D7 pulp temp. sensor
```

Next 1 2 3 4 5 6 7 8 Stop

Press NEXT to continue 4 D483 D4D0 0120