


USDA REPORT

08/20/86 19:00 GMT



HOLD \_\_\_\_\_ SENSOR \_\_\_\_\_ HOUR \_\_\_\_\_

	1	2	3	4	5	6	7
1A	1.2	1.0	1.2	1.1	1.5	1.2	1.2
1B	1.2	1.6	1.3	1.1	1.5	1.2	1.2
1C	1.4	1.2	1.2	1.5	1.3	1.4	1.4
1D	1.1	1.3	1.2	1.1	1.4	1.5	1.2
2A	1.3	1.2	1.3	1.2	1.5	1.2	1.2
2B	1.2	1.2	1.2	1.1	1.3	1.1	1.1
2C	1.8	2.2H	3.1H	2.2H	2.5H	1.9	1.5
2D	1.0	1.3	1.4	1.2	1.2	1.3	1.3
3A	1.2	1.1	1.2	1.2	1.3	1.1	1.5
3B	1.4	1.2	1.2	1.1	1.3	1.2	1.1
3C	1.2	1.1	1.1	1.2	1.1	1.2	1.1
3D	1.5	1.3	1.3	1.4	1.5	1.4	1.4
4A	1.3	1.1	1.2	1.2	1.3	1.2	1.1
4B	1.2	1.4	1.4	1.5	1.7	1.4	1.5
4C	1.3	1.2	1.1	1.3	1.2	1.4	1.5
4D	2.1	3.1H	2.5H	2.4H	1.9	2.5H	1.2

ALARM STATE INDICATOR

SAMPLE OF PRINTING