

MO SPRINTER

U. S. D. A.

Temps in °C

101 Test Input 0 C - 0.02  
102 Test Input +30 C 30.04

HOLD	Stbd Port			Space Probes							
	Air Del	Air Del	Air Ret	1	2	3	4	5	6	7	8
1A	- 0.01#	- 0.05#	- 0.17#	- 0.17#	- 0.27#	- 0.22#	- 0.15#	- 0.21#	- 0.14#	- 0.14#	
1B	- 0.07#	- 0.11#	- 0.01#	- 0.15#	- 0.28#	- 0.05#	- 0.07#	- 0.27#	- 0.08#	- 0.21#	
1C	- 0.11#	- 0.07#	- 0.06#	0.01#	- 0.02#	- 0.17#	- 0.10#	- 0.06#	- 0.10#		
1D	- 0.04#	0.09#	0.07#	- 0.02#	- 0.02#	0.01#	- 0.20#	0.11#			
2A	20.39#	20.48#	20.43#	19.43#	18.48#	18.15#	17.95#	19.67#	17.97#	18.36#	
2B	19.79#	20.29#	19.86#	17.13#	19.08#	17.47#	16.93#	16.74#	16.71#	17.71#	
2C	18.71#	18.59#	19.14#	16.06#	16.10#	15.33#	15.87#	15.91#	15.83#	15.98#	
2D	14.65#	15.79#	15.83#	15.28#	16.45#	15.27#	14.83#	15.14#	16.49#	14.17#	
2E	15.70#	15.72#	15.72#	14.94#	16.34#	15.22#	15.23#	15.61#	15.23#	15.25#	
3A	21.12#	21.04#	20.96#	21.21#	20.71#	21.32#	19.65#	20.65#	19.85#	19.21#	
3B	21.47#	21.42#	21.01#	20.66#	20.74#	21.61#	20.79#	20.83#	20.44#	20.76#	
3C	20.85#	20.73#	20.86#	20.42#	20.22#	20.29#	20.18#	20.36#	20.42#	20.41#	
3D	20.22#	19.50#	20.38#	19.83#	19.63#	19.37#	19.43#	19.89#	19.65#	20.46#	
3E	19.64#	19.54#	18.29#	19.38#	19.35#	19.09#	18.84#	19.06#	19.75#	18.94#	
4A	20.87#	20.69#	20.41#	20.10#	20.34#	21.86#	21.13#	20.04#	19.79#	20.01#	20.74#
4B	17.02#	17.58#	17.41#	17.24#	18.27#	17.88#	16.37#	17.18#	16.97#	17.09#	
4C	17.42#	17.36#	17.97#	16.12#	16.39#	16.20#	16.10#	16.32#	16.51#		
4D	18.40#	17.86#	17.39#	16.54#	16.59#	16.93#	17.65#	17.91#			

HOLD	Brine Del	Brine Ret	Humidity
1A	27.78#	27.93#	19.6#
1B	27.78#	28.24#	16.0#
1C	26.52#	28.21#	0.3#
1D	26.52#	22.00#	16.4#
2A	26.50#	26.79#	26.6#
2B	26.50#	27.05#	39.0#
2C	27.10#	26.64#	41.1#
2D	27.10#	27.12#	14.9#
2E	27.10#	27.17#	14.1#
3A	26.46#	27.69#	47.3#
3B	26.46#	27.57#	32.7#
3C	27.37#	27.76#	31.8#
3D	27.37#	27.59#	25.2#
3E	27.37#	27.59#	39.7#
4A	26.92#	27.56#	28.1#
4B	26.92#	27.94#	21.8#
4C	27.77#	27.94#	26.7#
4D	27.77#	28.14#	24.2#

*Hatch 1  
Print 1*