

INST.: HOLD4/A HOLD 4/A
 ZONE : 7

	REQUIRED TEMP.	CONTROL	OFF	ON
0-1	LOWER ALARM LEVEL		DEG.C	/
0-2	UPPER ALARM LEVEL		DEG.C	/
1-4	UPPER FW. HOLD4/A F148		0 DEG.C	/
2-4	UPPER AFT. HOLD4/A F149		0 DEG.C	/
3-4	FW. SS HOLD4/A F150		-1 DEG.C	/
4-4	FW. PS HOLD4/A F151		3 DEG.C	/
5-4	FW. PILL. SS HOLD4/A F152		1 DEG.C	/
6-4	AFT. PILL. SS HOLD4/A F153		0 DEG.C	/
7-4	AFT. PILL. PS HOLD4/A F154		-1 DEG.C	/
9-4	AFT. DIVIDER HOLD4/A F155		79.5 % R.H.	/

*2nd Floor
 410-11-A*

	REQUIRED TEMP.	CONTROL	OFF	ON
10-4	RET. AIR 1 HOLD4/A F236		0 DEG.C	/
11-4	DEL. AIR 1 HOLD4/A F237		0 DEG.C	/
12-4	DEL. AIR 2 HOLD4/A F238		0 DEG.C	/
13-4	RET. AIR 3 HOLD4/A F239		0 DEG.C	/
14-4	DEL. AIR 3 HOLD4/A F240		0 DEG.C	/
18-5	ALARM SIGNAL		DN OFF	/
19-1				/
21-4	UPPER FW. HOLD4/A F148		0 DEG.C	/
22-4	UPPER AFT. HOLD4/A F149		-1 DEG.C	/
23-4	FW. SS HOLD4/A F150		-1 DEG.C	/

Warmia
 Hull No. 364