






M/V Eagle Bay
Hull No. 865



DATE 88.12.11 10:58
DRAWN BY 12
SCALE 1:1000

Infekt ändringstade Alteration No.	Ritad Drawn	Kontrollerad Checked	Godkänd Approved	Aktionsnummer Archive No.	DF	UGF
	89.12.11				<input type="checkbox"/>	<input type="checkbox"/>

SNO 865 865
YARD: SHIKOKU, JAPAN
STAL'S NO: B-9673.0076

APPROVED

UNITED STATES DEPARTMENT OF AGRICULTURE
Animal and Plant Health Inspection Service
Fruit Inspection and Quarantine

9673.0076-14A

SYMBOL	QUANTITY	DESCRIPTION
△	30	USDA AIR SENSOR, FIXED
∇	74	USDA FRUIT SENSOR, PORTABLE

AIR SENSORS (FIXED)
SHALL BE LOCATED ON THE CENTRELINE OF THE VESSEL, APPROXIMATELY 30 CENTIMETERS FROM THE CEILING.
SHALL BE ATTACHED IN SUCH A WAY THAT THEY DON'T TOUCH THE BULKHEAD AND ARE PROTECTED FROM DAMAGE CAUSED BY THE CARGO.

FRUIT SENSORS (PORTABLE)
SHALL BE STORED IN RECESSED BOXES TO BE PROTECTED FROM DAMAGE WHEN NOT IN USE.
PROPOSAL OF BOXES FOR USDA FRUIT SENSORS. SEE DRAWING F-22731.