






Eastsea
Hull No.2596

SENSOR ARRANGEMENT FOR U.S.D.A. REPORT

TRUNK DECK
UPPER DECK
2ND DECK
3RD DECK
TANK TOP



● — FIXED SENSOR
● — NON-FIXED SENSOR