













U.S.D.A RECORDER

No.	No.1	No.2	No.3
1	A1	D1	G1
2	A2	D2	G2
3	A3	D3	G3
4	A4	D4	G4
5	A5	D5	G5
6	A6	D6	G6
7	B1	D7	G7
8	B2	D8	H1
9	B3	D9	H2
10	B4	E1	H3
11	B5	E2	H4
12	B6	E3	H5
13	B7	E4	H6
14	B8	E5	H7
15	C1	E6	H8
16	C2	E7	H9
17	C3	F1	
18	C4	F2	
19	C5	F3	
20	C6	F4	
21	C7	F5	
22		F6	
23		F7	
24		F8	
25		F9	



○ AIR SENSOR  
○ PULP SENSOR

SENSOR ARRANGEMENT FOR U.S.D.A REPORT

DAI NIPPON KEIYO MARU

HULL # 330

01-31-91