

DEL MONTE PLANTER VOYAGE NO. 12 GMT DATE: 06 05 18 TIME: 10 12

USDA REPORT

SENSOR NO.

HOLD 1 2 3 4 5 6

1A 20.4 20.6 20.5 23.3 20.5
 1B 19.4 19.2 19.7 19.5
 1C 20.8 20.9 21.2 20.5
 1D 20.6 21.6 21.2

2A 19.6 20.7 19.3 19.5 19.6
 2B 17.8 18.5 18.3 18.3 18.0
 2C 17.7 17.7 17.6 17.8
 2D 17.4 17.5 17.5 17.2 17.2

3A 19.3 19.3 19.1 19.0 19.7
 3B 17.9 18.1 18.3 18.3 18.2
 3C 17.3 17.2 17.4 17.1 17.2
 3D 16.4 16.6 17.3 17.3 16.8

4A 19.9 20.4 20.1 19.8 19.9
 4B 19.1 19.3 19.3 19.0
 4C 17.7 18.6 18.0 17.9 18.0
 4D 17.6 17.6 17.5 17.5 18.4

HLL TEMPERATURES IN DEGREES CENTIGRADE

> = HIGH ALARM, < = LOW ALARM, D = DEFROSTING

Planter
 Hull# 270
 IMO# 8713574